










Lathe Finish

Tools

Profiles

Parameters

Tools List:

C:\ProgramData\SimplyC... \Lathe_mm.rlb

Generic OD 04 15° (Radius 0.4)

Generic OD 08 15° (Radius 0.8)

Generic OD 04 30° (Radius 0.4)

Generic OD 08 30° (Radius 0.8)

Generic ID 04 5° (Radius 0.4)

Generic ID 08 5° (Radius 0.8)

Click on the same
tool

Spindle Off

Feed rate: 0.1

mm/giro ☒mm/min ☐Coolant ☐

Tool geometry



Name: Generic OD 04 15°

Type: General OD turning

Corner radius: 0.4

Compensation: Tip

Open library

Save library

Add to lib.

Modify in lib.

Change Post

Run Post

Show/Hide toolpaths

X: -21.1 Y: 12.921

Define tool, speed and feeds

SHAP
OFF

90°



Livello corrente: 0

2.014
mm

Lathe Finish

Tools

Profiles

Parameters

Profiles definition:

☐ Layer p

Profile definition

 Select WinSelect Chain Reverse Unselect last Unselect all Chains Manager

Cutter Compensation:

Offset Side: Right

Cutter compensation in Cnc (G41/G42) ☐

Change Post

Run Post

Show/Hide toolpaths

X: -21.1 Y: 12.921

Select the profile, cutter compensation and Entry/Exit

SNAP
OFF

90°



Livello corrente: 0




Lathe Finish

Tools

Profiles

Parameters

Profiles definition:

☐ Layer priority

Last



Select



Chain



Reverse



Unselect last



Unselect all



Chains Manager

Cutter Compensation:

Offset Side: Right

Cutter compensation in Cnc (G41/G42) ☐

Last: defines the profile used in the previous operation

Change Post

Run Post

Show/Hide toolpaths

X: -21.1 Y: 12.921

Select the profile, cutter compensation and Entry/Exit

SNAP
OFF

90°



Livello corrente: 0

2.014
mm

Lathe Finish

Tools

Profiles

Parameters

Profiles definition:

☐ Layer priority

Go To

Last

All

Select

WinSelect

Chain

Reverse

Unselect last

Unselect all

Chains Manager

1 open chain

Cutter Compensation:

Offset Side:

Right

Off

Right

Left

Cutter compensation in Cnc (G41/G42)

Definition of tool compensation (on the right of the chained profile)

Change

Show/Hide toolpaths

X: -21.1 Y: 12.921

Select the profile, cutter compensation and Entry/Exit

SNAP OFF

90°

Grid

Snap

Grid

STOP

✓

Livello corrente: 0

■

Lathe Finish

Tools

Profiles

Parameters

Profiles definition:

☐ Layer priority

Go To

Last

All

Select

WinSelect

Chain

Reverse

Unselect last

Unselect all

Chains Manager

1 open chain

Cutter Compensation:

Offset Side:

Right

Off

Right

Left

Cutter compensation in Cnc (G41/G42) ☐

Change Post

Run Post

Show/Hide toolpaths

X: -21.1 Y: 12.921

Select the profile, cutter compensation and Entry/Exit

OFF

90

L

J

H

STOP

✓

Livello corrente: 0

Line Endpoints Rectangle Circle Ct + Pt Polyline Spline TrueType
Zoom In Zoom back Zoom window Pan Redraw Top Front Side

Large arrow = cut direction
Small arrow = compensation direction

Lathe Finish

Tools

Profiles

Parameters

Finish parameters:

☐ Face toolpath

☐ Lead in... (0

☐ Lead out... (0 @ 0°)

Stock to leave: 0

N. 1

Finish cut size: 0

☐ Home position: X40, Z5

Calculate

Cancel

Change Post

Run Post

Show/Hide toolpaths

X: -21.1 Y: 12.921

Set the cutting parameters and press the 'Calculate' button

SNAP OFF

90°

Grid

Layers

Grid

STOP

✓

Livello corrente: 0

Parameters



2.014 mm

Lathe Finish

Tools

Profiles


Parameters

Finish parameters:

☐ Face toolpath

☐ Lead in... (0 @ 0°)

☐ Lead out... (0 @ 0°)



Stock to leave: 0

N. 1

Finish cut size: 0

☐ Home position: X40, Z5

Calculate

Machining calculation

Change Post

Run Post

Show/Hide toolpaths

X: -21.1 Y: 12.921

Set the cutting parameters and press the 'Calculate' button

SNAP OFF

90°

Grid


Layer


Stop


Check




Livello corrente: 0

2.014 mm









.....
.....

Line: 1/5

⏮ ⏪ ⏩ ⏭ ⏸

Step (F5)

☒ Show Tool


☐ Solid simulation




☐ GCode simulation

⏮ ⏪ ⏩ ⏭ ⏸

Change Post Run Post

Show/Hide toolpaths





.....

Line: 2/5

⏮ ⏪ ⏩ ⏭

Step (F5)

☒ Show Tool


☐ Solid simulation

☐ GCode simulation

Change Post

Run Post





Show/Hide toolpaths





2.014
mm

X: -21.18 Y: 6.676



.....

Line: 5/5

⏮ ⏪ ⏩ ⏭ ⏸

Step (F5)


☒ Show Tool


☐ Solid simulation

☐ GCode simulation

Change Post Run Post

Show/Hide toolpaths





Lathe Finish

Tools

Profiles

Parameters

Finish parameters:

☐ Face toolpath☒ Lead in... (0 @ 0°)☐ Lead out... (0 @ 0°)

Stock to leave: 0

N. 1

Finish cut size: 0



Home position: X40, Z5

Calculate

Cancel

Change Post

Run Post

Show/Hide toolpaths

X: -20.979 Y: 14.895

Set the cutting parameters and press the 'Calculate' button

SNAP OFF

90°



Current layer: 0




Add the Lead In

2.014
mm

Entry vector

Entry length:

Direction(degrees):



Ok

Calculate

Cancel

Change Post

Run Post

Show/Hide toolpaths

X: -20.979 Y: 14.895

Set the cutting parameters and press the 'Calculate' button

SNAP OFF

90°



Current layer: 0



Define the length and direction of the Entry vector

2.014
mm

Lathe Finish

Tools

Profiles

Parameters

Finish parameters:

☐ Face toolpath

☒ Lead in... (1 @ 180°)

☒ Lead out... (0 @ 0°)

Stock to leave: 0

N. 1

Finish cut size: 0

☐ Home position: X40, Z5

Calculate

Cancel

Change Post

Run Post

Show/Hide toolpaths

X: -20.979 Y: 14.895

Set the cutting parameters and press the 'Calculate' button

SNAP OFF

90°

Y

X

STOP

✓

Current layer: 0


Add the Lead Out

2.014 mm

Exit vector

Exit length:

Direction(degrees):



Ok

Calculate

Cancel

Define the length and
direction of the Exit vector

Change Post

Run Post

Show/Hide toolpaths

X: -20.979 Y: 14.895

Set the cutting parameters and press the 'Calculate'
button

SNAP
OFF

90°



Current layer: 0



Lathe Finish


Tools
Profiles
Parameters

Finish parameters:

☐ Face toolpath

☒ Lead in... (1 @ 180°)

☒ Lead out... (1 @ 45°)



Stock to leave:

N.

Finish cut size:

☒ Home position: X40, Z5

Execute the recalculation of machining with the new parameters

Line Endpoints
Rectangle
Circle Ct + Pt
Polyline
Spline
TrueType

Zoom In
Zoom back
Zoom window
Pan
Redraw
Top
Front
Side

Change Post
Run Post

Show/Hide toolpaths




2.014 mm





X: -20.616 Y: 5.83

Set the cutting parameters and press the 'Calculate' button



SNAP OFF
90°
Y
X
STOP
✓

Current layer: 0










X: -22.419 Y: 10.563



Passo a passo





.....

 |

Line:3/7

⏮ ⏪ ⏩ ⏭ ⏸


⏮ ⏪ ⏩ ⏭ ⏸





☒ Show Tool
☐ Solid simulation
☐ GCode simulation

⏮ ⏪ ⏩ ⏭ ⏸




Change Post Run Post

Show/Hide toolpaths





X: -22.419 Y: 10.563




Line: 5/7

☒ Show Tool
☐ Solid simulation
☐ GCode simulation

Change Post Run Post


Show/Hide toolpaths



X: -22.419 Y: 10.563

Create point Line Endpoints Rectangle Circle Ct + Pt Polyline Spline TrueType

Autozoom Zoom In Zoom back Zoom window Pan Redraw Top Front Side



Step (F5)

- ☒ Show Tool
- ☐ Solid simulation
- ☐ GCode simulation

[Change Post](#)

Run Post

Show/Hide toolpaths

X: -22.419 Y: 10.563

SNAP
OFF

90'



Livello corrente: 0




Line: 7/7


Step (F5)

☒ Show Tool
☐ Solid simulation
☐ GCode simulation

Change Post Run Post

Show/Hide toolpaths





New Open Vectorize Save Machine

Undo Delete Fillet Translate

Geometry Toolpath

Macchina: TurnMach2-3

- Lathe Rough R.0.4 (Generic OD 0.4)
- Parameters
- Toolpath (61)
- Lathe Finish R.0.4 (Generic OD 0.4)
- Parameters
- Toolpath (7)

Change Post Run Post

Show/Hide toolpaths

X: -19.708 Y: 17.765

gcEditor v 0.9.9.2

File Edit Text Tools Help

C:\ProgramData\SimplyCam 3\gcode\test.nc


```
N22 X24.2
N23 G01 Z0.1
N24 Z-19.9
N25 X26.2
N26 X26.907 Z-19.546
N27 G00 Z1.1
N28 X22.2
N29 G01 Z0.1
N30 Z-19.9
N31 X24.2
N32 X24.907 Z-19.546
N33 G00 Z1.1
N34 X20.2
N35 G01 Z0.1
N36 Z-19.9
N37 X22.2
N38 X22.907 Z-19.546
N39 G00 Z1.1
N40 X18.2
N41 G01 Z0.1
N42 Z-8.282
N43 X20.094 Z-10.176
N44 G03 X20.2 Z-10.4 I-0.444 K-0.223
N45 G01 X20.907 Z-10.046
N46 G00 Z1.1
N47 X16.2
```

In 0 col 0

Current Z: 0

2.223 mm

Livello corrente: 0



The screenshot displays the SimplyCam 3 software interface. The main window shows a 3D model of a lathe part with a toolpath overlay. The toolpath is labeled 'Toolpath (61)' and 'Toolpath (7)'. The G-code editor window is open, showing the following code:

```
gcEditor v 0.9.9.2
File Edit Text Tools Help
C:\ProgramData\SimplyCam 3\gcode\finish.nc

%
N1 (POST PROCESSOR: TURNMACH2-3)
N2 (FINISH.NC)
N3 G21 (UNITS: MM)
N4 G18 G40 G49 G80 G90
N5 (TOOL/STANDARD, 15, 70, 0.4, 10,3)
N6 T1 M6 (TLDIA=0.4)
N7 S300 M3
N8 G43 H1 S0
N9 G00 Z0.779
N10 X9.916
N11 G00 Z0.
N12 X0.779 Y4.958
N13 G01 X-0.221 Y4.958 Z0. F0.1
N14 X-10.221 Y9.958
N15 G03 X-10.4 Y10. I-0.358 K-
N16 G01 X-20.
N17 Y14.6
N18 X-19.293 Y15.307
N19 G00 Z0.
N20 M05
N21 M30
%
```

A yellow callout bubble points to the G-code file, stating: "The G-Code file with only the Finishing operation is created".

The interface includes a toolbar with buttons for New, Open, Vectorize, Save, Machine, Undo, Delete, Fillet, and Translate. The Geometry tab is active, showing a tree view of the model structure. The bottom status bar displays coordinates X: -6.994 Y: 9.674 and a current Z value of 0.