

New Open Vectorize Save as Machining Settings Help

Create point Line Endpoints Rectangle Circle Ct + Pt


Undo Delete Split Translate

Side Iso

Geometry Toolpath

Machine: LaserGBRL  
Laser Cut D.0.3 (Laser Set1)  
Parameters  
Toolpath (138)

In questo semplice tutorial viene mostrato come creare un percorso per tagliare il pezzo con un a macchina Laser, Plasma o WaterJet.



Change Post

Run Post

Show/Hide toolpaths

X: 1.574 Y: 9.245

SNAP  
OFF

90°

Grid

Grid

STOP


Green checkmark

Current layer: 0 Label1

New Open Vectorize Save Machining Settings Help Close Create point Line Endpoints Rectangle Circle Ct + Pt

Carica

Geometry




Scegliere "SAMPLE\_IPAD-BASE.DXF"

File: New, Open, Vectorize, Save, Machining, Settings, Help, Close  
Tools: Create point, Line Endpoints, Rectangle, Circle Ct + Pt  
Edit: Undo, Delete, Fillet, Translate, Select  
View: Autozoom, Zoom In, Zoom back, Zoom window, Pan, Redraw  
Orientation: Top, Front, Side, Iso


Geometry | Toolpath

- Layer:0
  - Arc
  - Arc
  - Line
  - Arc
  - Line
  - Arc
  - Polyline
  - Arc
  - Line
  - Arc
  - Arc
  - Line
  - Arc
  - Line
  - Arc




X: 25.768 Y: -6.538

SHAP OFF | 90° | [Grid] | [Snap] | [Lock] | [Stop] | [Check] | Current layer: 0 | Label1



Selezionare Zoom Window


Geometry Toolpath



Divide:

	X	Y
Point 1:	-95	9.396
Point 2:	0	9.396


Update



19.267  
mm

X: -38.719 Y: 43.346

SNAP OFF 90° [Grid] [Snap] [Lock] [Zoom] [Pan] [Redraw] [Top] [Front] [Side] [Iso] Current layer: 0 Label1



Geometry Toolpath

Arc  
Line

Click nel primo punto

Arc  
Arc  
Line  
Arc  
Line  
Arc  
Line  
Arc  
Line

Divide:

	X	Y
Point 1:	-95	9.396
Point 2:	0	9.396

Update


1/2




19.267  
mm

X: -38.719 Y: 43.346

SNAP OFF 90° [Grid] [Snap] [Lock] [Stop] [Check] Current layer: 0 Label1



## Geometry Toolpath




Divide:

	X	Y
Point 1:	-95	9.396
Point 2:	0	9.396

Update

1/2



Click nel secondo punto

19.267  
mm

X: 43.735 Y: -34.68

Select the second point of the area.



Current layer: 0 Label1

New Open Vectorize Save Machining Settings Help Close
Create point Line Endpoints Rectangle Circle Ct + Pt

Undo Delete Split Translate Select
Autozoom Zoom In Zoom back Zoom window Pan Redraw
Top Front Side Iso


Geometry **Toolpath**

- Arc
- Line
- Arc
- Polyline
- Arc
- Line
- Arc
- Arc
- Line
- Arc
- Line
- Arc
- Line
- Arc
- Line
- Line

Divide:



	X	Y
Point 1:	-95	9.396
Point 2:	0	9.396

Update





X: 20.613 Y: -8.786

SNAP OFF 90° Grid Layers Grid STOP Check
Current layer: 0 Label1



Creazione nuova operazione.  
Selez. "Laser Cut" dal  
menu Lavorazioni.



X: -83.843 Y: 84.612





New Open Vectorize Save Machining Settings Help Close Create point Line Endpoints Rectangle Circle Ct + Pt

Undo De Laser Cut Laser, Plasma, ... Profiles Parameter Pan Redraw Top Front Side Iso

Laser, Plasma, ...

Profiles

Parameter

List

C:\ProgramData\SimplyCa... \Laser\_mm.llb

Laser Set1(Diam. 0.3)

Laser Set2(Diam. 0.35)


Laser Set3(Diam. 0.4)

Info

Number: 0

Power: 0

Power(min.): 0

Kerf Diameter: 

Feed rate: 100

Feed rate(2): 0

Pierce delay: 50

Pause at end: 50

Name: Laser Set1

Impostare parametri tecnologici  
esempio:  
Diametro  
Avanzamento

Open library

Save library

Add to lib.

Modify in lib.

Change Post

Run Post

Show/Hide toolpaths

X: -101.15 Y: 86.535

Select the profile, cutter compensation and  
Enter/Exit

SNAP  
OFF

90°


























Current layer: 0  Label1

9.59  
mm

**Laser Cut**

Laser, Plasma, Profiles Parameter

Profiles definition:

Layer profile

**Definizione Profilo**

Select WinSelect

Chain Reverse

Unselect last Unselect all Chains Manager

Cutter Compensation:

Offset Side: Off


Offset distance: 0.15

Start in mid

Cutter compensation in Cnc (G41/G42)

Close Create point Line Endpoints Rectangle Circle Ct + Pt

Zoom In Zoom back Zoom window Pan Redraw Top Front Side Iso



Change Post Run Post

Show/Hide toolpaths

1/2

X: -38.464 Y: 16.917

**Laser Cut**

Laser, Plasma, Profiles Parameter

Profiles definition:

Layer profile

**Definizione Profilo**

Select WinSelect

**Selez. Catena**

Chain

Unselect last Unselect all Chains Manager

Cutter Compensation:

Offset Side: Off

Offset distance: 0.15

Start in mid

Cutter compensation in Cnc (G41/G42)

Close Create point Line Endpoints Rectangle Circle Ct + Pt

Zoom In Zoom back Zoom window Pan Redraw Top Front Side Iso

Change Post Run Post

Show/Hide toolpaths

1/2

X: -38.464 Y: 16.917

**Laser Cut**

Laser, Plasma, ...   Profiles   Parameter

Profiles definition:

Layer priority

Go To

Last   All

Select   WinSelect

Chain   Reverse

Unselect last   Unselect all   Chains Manager

1 closed chain

Cutter Compensation:

Offset Side: Off


Offset distance: 0.15

Start in mid

Cutter compensation in Cnc (G41/G42)

Close   Create point   Line Endpoints   Rectangle   Circle Ct + Pt

Zoom In   Zoom back   Zoom window   Pan   Redraw   Top   Front   Side   Iso



Click sul profilo per definire la gemetria della lavorazione

Change Post   Run Post

Show/Hide toolpaths

X: 9.68 Y: 7.518

**Laser Cut**

Laser, Plasma, ...   Profiles   Parameter

Profiles definition:

Layer priority

Go To

Last

Select

Chain

Unselect last   Unselect all

1 closed chain

Cutter Compensation:

Offset Side: Off

Offset distance: 0.15


Start in mid

Cutter compensation in Cnc (G41/G42)

Premere Catena o il  
tasto "C" nella tastiera

Close   Create point   Line Endpoints   Rectangle   Circle Ct + Pt

Zoom In   Zoom back   Zoom window   Pan   Redraw   Top   Front   Side   Iso



Change Post   Run Post

Show/Hide toolpaths

X: -33.093 Y: 22.479

9.59 mm

**Laser Cut**

Laser, Plasma, ...    Profiles    Parameter

Profiles definition:

Layer priority

Go To

Last    All

Select    WinSelect

Chain    Reverse

Unselect last    Unselect all    Chains Manager

2 closed chain

Cutter Compensation:

Offset Side: Off

Offset distance: 0.15

Start in mid

Cutter compensation in Cnc (G41/G42)

Close    Create point    Line Endpoints    Rectangle    Circle Ct + Pt

Zoom In    Zoom back    Zoom window    Pan    Redraw    Top    Front    Side    Iso

Click sul profilo per definire la geometria della lavorazione

Change Post    Run Post

Show/Hide toolpaths

1/2

X: 17.353 Y: 8.094

**Laser Cut**

Laser, Plasma, ...   Profiles   Parameter

Profiles definition:

Layer priority

Go To

Last

Select

Chain

Unselect last   Unselect all

2 closed chain

Cutter Compensation:

Offset Side: Off

Offset distance: 0.15


Start in mid

Cutter compensation in Cnc (G41/G42)

Premere Catena o il  
tasto "C" nella tastiera

Close   Create point   Line Endpoints   Rectangle   Circle Ct + Pt

Zoom In   Zoom back   Zoom window   Pan   Redraw   Top   Front   Side   Iso



Change Post   Run Post

Show/Hide toolpaths

1/2

X: -32.326 Y: 26.891

9.59 mm

**Laser Cut**

Laser, Plasma, ...   Profiles   Parameter

Profiles definition:

Layer priority

Go To

Last   All

Select   WinSelect

Chain   Reverse

Unselect last   Unselect all   Chains Manager

3 closed chain

Cutter Compensation:

Offset Side: Off


Offset distance: 0.15

Start in mid

Cutter compensation in Cnc (G41/G42)

Close   Create point   Line Endpoints   Rectangle   Circle Ct + Pt

Zoom In   Zoom back   Zoom window   Pan   Redraw   Top   Front   Side   Iso



Click sul profilo per definire la geometria della lavorazione

Change Post   Run Post

Show/Hide toolpaths

1/2

X: 28.669 Y: 18.835



**Laser Cut**

Laser, Plasma, ...   Profiles   Parameter

Profiles definition:

Layer priority

Go To

Last   All

Select   WinSelect

Chain   Reverse

Unselect

3 closed chain

Cutter Compensation:

Offset Side: **Outside**

Offset dist: **Outside**

Start in mid

Cutter compensation in Cnc (G41/G42)

1) Selezionare compensazione su: Esterno

Close   Create point   Line Endpoints   Rectangle   Circle Ct + Pt

Zoom In   Zoom back   Zoom window   Pan   Redraw   Top   Front   Side   Iso

Change Post   Run Post

Show/Hide toolpaths

1/2

X: -31.367 Y: 24.973

9.59 mm

**Laser Cut**

Laser, Plasma, ...   Profiles   Parameter

Profiles definition:

Layer priority

Go To

Last   All

Select   WinSelect

Chain   Reverse

Unselect

3 closed chain

Cutter Compensation:

Offset Side: **Outside**

Offset dist: **Outside**

Start in mid

Cutter compensation in Cnc (G41/G42)

1) Selezionare compensazione su: Esterno

Close   Create point   Line Endpoints   Rectangle   Circle Ct + Pt

Zoom In   Zoom back   Zoom window   Pan   Redraw   Top   Front   Side   Iso

2) La freccia piccola indica la direzione della compensazione

Change Post

Show/Hide toolpaths

X: -31.367 Y: 24.973

**Laser Cut**

Laser, Plasma, ...   Profiles   Parameter

Profiles definition:

Layer priority

Go To

Last   All

Select   WinSelect

Chain   Reverse

Unselect last   Unselect all   **Chains Manager**

3 closed chain

Cutter Compensation:

Offset Side: Outside


Offset distance: 0.15

Start in mid

Cutter compensation in Cnc (G41/G42)

Close   Create point   Line Endpoints   Rectangle   Circle Ct + Pt

Zoom In   Zoom back   Zoom window   Pan   Redraw   Top   Front   Side   Iso




Premere Gestione Catene per cambiare il punto di partenza della lavorazione

Change Post   Run Post

Show/Hide toolpaths

1/2



1) Selezionare Catena 1

- 1 closed chain
- 2 closed chain
- 3 closed chain

Delete selected

Start point:

Ok

Cutter compensation in Cnc (G41/G42)

Change Post

Run Post

Show/Hide toolpaths

X: -31.367 Y: 24.973

SHAP OFF 90° Current layer: 0 Label1

9.59 mm

Chain settings

- 1 closed chain
- 2 closed chain
- 3 closed chain

Delete selected

Start point:

Ok

Cutter compensation in Cnc (G41/G42)

1) Selezionare Catena 1

2) Muovere il punto di partenza

Head-base.DXF

Line Endpoints Rectangle Circle Ct + Pt

Zoom In Zoom back Zoom window Pan Redraw Top Front Side Iso

9.59 mm

X: -31.367 Y: 24.973

SNAP OFF 90°

Current layer: 0 Label1

**Chain settings**

- 1 closed chain
- 2 closed chain
- 3 closed chain

Delete selected

Start point:


Ok

Cutter compensation in Cnc (G41/G42)

1) Selezionare Catena 3

Close Create point Line Endpoints Rectangle Circle Ct + Pt

Zoom window Pan Redraw Top Front Side Iso



Change Post Run Post

Show/Hide toolpaths

1/2

X: -31.367 Y: 24.973

9.59 mm

Chain settings

- 1 closed chain
- 2 closed chain
- 3 closed chain

Delete selected

Start point:

1) Selezionare Catena 3

2) Muovere il punto di partenza

ad-base.DXF

Close Create point Line Endpoints Rectangle Circle Ct + Pt

Zoom window Pan Redraw Top Front Side Iso

Change Post Run Post

Show/Hide toolpaths

X: -31.367 Y: 24.973

9.59 mm

SHAP OFF 90°


Current layer: 0 Label1

**Laser Cut**

Laser, Plasma, ... Profiles **Parameter**

Cut parameters:

Laser feed plane: 2



Stock to leave: 0

Lead In/Out (none)

Num. of passes: 1

Holding Tabs

Calculation Method: Standard


Cutting rules: None

Transform Calculate Cancel

Parametri operazione

Circle Ct + Pt

Zoom In Zoom back Zoom window Pan Redraw Top Front Side Iso



9.59 mm

Change Post Run Post

Show/Hide toolpaths

1/2

X: -31.367 Y: 24.973

Set the cutting parameters and press the 'Calculate' button




**Laser Cut**

Laser, Plasma, ... Profiles **Parameter**

Cut parameters:

Laser feed plane: 2



Stock to leave: 0

Lead In/Out (none)

Num. of passes: 1


Holding Tabs

Calculation Method: Standard

Cutting rules: None

Transform Calculate Cancel

Definire attacchi di  
Entrata/Uscita al profilo



Change Post Run Post

Show/Hide toolpaths

X: -31.367 Y: 24.973

Set the cutting parameters and press the 'Calculate' button

Entry / Exit

Lead in:  Lead out:

Lead in: Line

Size: 1

Impostare Ingresso: Linea  
Dimensione: 1

Ok

Stock to leave: 0

Lead In/Out (none)

Num. of passes: 1

Holding Tabs

Calculation Method: Standard

Cutting rules: None

Transform


Calculate

Cancel

Change Post

Run Post

Show/Hide toolpaths



9.59 mm

X: -31.367 Y: 24.973

Set the cutting parameters and press the 'Calculate' button

Entry / Exit

Lead in:  
Lead in: Line  
Size: 1

Lead out:  
Lead out: Line  
Size: 1



Click per fare Uscita uguale

Stock to leave:

Lead In/Out (none)

Num. of passes: 1

Holding Tabs

Calculation Method: Standard

Cutting rules: None

Transform

Calculate

Cancel



Change Post

Run Post

Show/Hide toolpaths



9.59 mm



X: -31.367 Y: 24.973


Set the cutting parameters and press the 'Calculate' button

**Laser Cut**

Laser, Plasma, ...   Profiles   Parameter

Cut parameters:

Laser feed plane:



Stock to leave:

Lead in: 1 Lead out: 1

Num. of passes:

Holding Tabs

Calculation Method:


Cutting rules:

Premere "Calcola"

Close   Create point   Line Endpoints   Rectangle   Circle Ct + Pt


Zoom In   Zoom back   Zoom window   Pan   Redraw   Top   Front   Side   Iso



X: -31.367 Y: 24.973   Set the cutting parameters and press the 'Calculate' button

SHAP OFF   90°               STOP      Current layer: 0   Label1

9.59 mm




Geometry | Toolpath

- Machine: GRBL-Laser
  - Laser Cut D.0.3 (Laser Set1)
    - Parameters
    - Toolpath (138)


Change Post    Run Post

Show/Hide toolpaths

Operazione Laser Cut creata




X: -17.387 Y: 3.821



Geometry Toolpath

- Machine: GRBL-Laser
  - Laser Cut D.0.3 (Laser Set1)
    - Parameters
    - Toolpath (138)

Parametri utilizzati




Change Post Run Post

Show/Hide toolpaths

X: -17.387 Y: 3.821

SHAP OFF 90° [Grid] [Snap] [STOP] [Checkmark] Current layer: 0 Label1




Geometry | Toolpath

- Machine: GRBL-Laser
  - Laser Cut D.0.3 (Laser Set1)
    - Parameters
    - Toolpath (138)**



Change Post    Run Post

Show/Hide toolpaths

Percorso creato





X: -17.387 Y: 3.821



Select Postprocessor

Tasto destro del mouse su "Macchina" e Seleziona Postprocessor



Estimate machining time = 0h, 10m, 04s

X: -10.246 Y: 8.879





Select postprocessor

Post Processor

GRBL-Laser

Post GRBL-Laser  
 No Modal G code, XY  
 No Z move  
 M3/M5 Laser On/Off  
 S0-S255 Laser power grayscale  
 Space between instruction  
 No Block number

Output metric  Output inch


Output file extension:

Rapid feedrate:

Edit Ok

Help Close Create point Line Endpoints Rectangle Circle Ct + Pt


Autozoom Zoom In Zoom back Zoom window Pan Redraw Top Front Side Iso



Change Post Run Post


Show/Hide toolpaths

1/2



Geometry | Toolpath


- Machine: GRBL-Laser
  - Laser Cut D.0.3 (Laser Set1)
    - Parameters
    - Toolpath (138)



Eeguire il Postprocessor

Change Post | Run Post | Show/Hide toolpaths

Estimate machining time = 0h, 10m, 04s



Inserire il nome del file  
G-Code e click su Salva

Change Post

Run Post

Show/Hide toolpaths

Estimate machining time = 0h, 10m, 04s

1.83  
mm

X: -9.587 Y: 9.171

Define the postprocessor

SHAP  
OFF

90°

G

L

G

STOP

✓

Current layer: 0

Label1

gcEditor v 0.9.9.2

File Edit Text Tools Help

C:\ProgramData\SimplyCam 3\gcode\test.nc

```
G28; home all axes
G21; Set units to millimeters
G90; Use absolute coordinates
G92; Coordinate Offset
G00X-6.315Y1.251
M4
M18
G01X-7.315Y1.251F100
G01X-7.315Y3.057
G03X-8.465Y4.207I-1.15J0.
G01X-59.001Y4.211
G03X-59.151Y4.061I0.J-0.15
G01X-59.151Y-15.789
G01X-63.551Y-15.789
G01X-63.549Y4.061
G03X-63.699Y4.211I-0.15J0.
G01X-94.Y4.214
G03X-95.15Y3.064I0.J-1.15
G01X-95.15Y-2.269
G03X-95.08Y-2.665I1.151J0.
G01X-88.514Y-20.558
G03X-87.038Y-21.241I1.08J0.396
G01X-85.713Y-20.755
G03X-82.674Y-15.321I-1.644J4.487
G01X-84.338Y-10.049
G02X-83.814Y-8.983T0.812.T0.263
```

In 0 col 0




Current Z: 0 Sim

me = 0h, 10m, 04s



1.83 mm

Current layer: 0 Label1

Questo è il file G-Code da eseguire sul CNC



Selezionare GRBL Panel dal menu



Estimate machining time = 0h, 10m, 05s

1.855 mm

X: -6.478 Y: 6.64



SimplyLaser

New Open Vectorize Save Mach

Undo Delete Fillet Translate S

Geometry Toolpath

Geometry

X: -16.225 Y: 14.015

### GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
 **Aprire la porta di comunicazione**

Machine Status:  
Active State:  
**Idle**

X **-35.168**  
Y **-12.100**  
Z **-2.000**

Show position

Show verbose output

Grbl 0.9j ['\$' for help]

Machine Control | File Mode | Macros

Command:

Machine Control:  
Zero XYZ Step Size 1  
Zero X Y+ Z+  
Zero Y X- X+  
Zero Z Y- Z-  
G54 G55 G56 G57 G58 G59

3.157 mm

Label1

SimplyLaser

New Open Vectorize Save Mach

Undo Delete Fillet Translate S

Geometry Toolpath

Geometry

X: -16.225 Y: 14.015

### GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
Close

Panic Button

Machine Status:  
Active State:  
**Idle**

X **-43.168**  
Y **-12.100**  
Z **-2.000**

Work Coord's  
 Show position

Show verbose output

Grbl 0.9j ['\$' for help]  
Grbl 0.9j ['\$' for help]  
[G0 G54 G17 G21 G90 G94 M0 M5 M9 T0 F0. S0.]

Machine Control | File Mode | Macros

Command:  
[\$H] Run homing cycle    [\$#] View gcode paramet  
[\$X] Kill Alarm        [\$G] View parser state

Machine Control:  
Zero XYZ    Step Size 1  
Zero X    Y+    Z+  
Zero Y    X-    X+  
Zero Z    Y-    Z-

Colapse    Close

Muovere e azzerare gli assi del Cnc

3.157 mm

Label1

SimplyLaser

New Open Vectorize Save Mach

Undo Delete Fillet Translate S

Geometry Toolpath

Geometry

X: -16.225 Y: 14.015

### GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
Close

Panic Button

Machine Status:  
Active State:  
**Run**

X **-43.856**  
Y **-12.100**  
Z **-2.000**

Work Coord's  
 Show position

Show verbose output

Grbl 0.9j ['\$' for help]  
Grbl 0.9j ['\$' for help]  
[G0 G54 G17 G21 G90 G94 M0 M5 M9 T0 F0. S0.]

Machine Control | File Mode | Macros

Command:  
[\$H] Run homing cycle    [\$#] View gcode paramet  
[\$X] Kill Alarm        [\$G] View parser state

Machine Control:  
Zero XYZ    Step Size 1  
Zero X    Y+    Z+  
Zero Y    X-    X+  
Zero Z    Y-    Z-

Colapse    Close

Muovere e azzerare gli assi del Cnc

3.157 mm

Label1



SimplyLaser

New Open Vectorize Save Mach

Undo Delete Fillet Translate S

Geometry Toolpath

Geometry

X: -16.225 Y: 14.015

### GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
Close

Panic Button

Machine Status:  
Active State:  
**Run**

X **-39.876**  
Y **-12.100**  
Z **-2.000**

Work Coord's  
 Show position

Show verbose output

Grbl 0.9j ['\$' for help]  
Grbl 0.9j ['\$' for help]  
[G0 G54 G17 G21 G90 G94 M0 M5 M9 T0 F0. S0.]

Machine Control | File Mode | Macros

Command:  
[\$H] Run homing cycle    [\$#] View gcode paramet  
[\$X] Kill Alarm        [\$G] View parser state

Machine Control:  
Zero XYZ    Step Size 1  
Zero X    Y+    Z+  
Zero Y    X-    X+  
Zero Z    Y-    Z-

Colapse    Close

Muovere e azzerare gli assi del Cnc

3.157 mm

Label1

SimplyLaser

New Open Vectorize Save Mach

Undo Delete Fillet Translate S

Geometry Toolpath

Geometry

X: -16.225 Y: 14.015

### GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
Close

Panic Button

Machine Status:  
Active State:  
**Idle**

X **-44.168**  
Y **-12.100**  
Z **-2.000**

Work Coord's

Show position

Show verbose output

Grbl 0.9j ['\$' for help]  
Grbl 0.9j ['\$' for help]  
[G0 G54 G17 G21 G90 G94 M0 M5 M9 T0 F0. S0.]

Machine Control | File Mode | Macros

Command:  
[\$H] Run homing cycle [\$#] View gcode paramet

Machine Control:  
Zero XYZ  
Zero X  
Zero Y  
Zero Z

Step Size 1

X- X+ Y+ Y- Z+ Z-


G54 G55 G56 G57 G58 G59

Colapse Close

Muovere e azzerare gli assi del Cnc

3.157 mm

Label1



GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
Close

Panic Button

Machine Status:  
Active State:  
Idle  
X 0.000  
Y 0.000  
Z 0.000

Work Coord's  
 Show position

Show verbose output

```
Grbl 0.9j ['$' for help]
Grbl 0.9j ['$' for help]
[G0 G54 G17 G21 G90 G94 M0 M5 M9 T0 F0. S0.]
[G0 G54 G17 G21 G90 G94 M0 M5 M9 T0 F0. S0.]
```

Machine Control | File Mode | Macros

Command:  
[\$H] Run homing cycle | [\$#] View gcode parameters

Muovere e azzerare gli assi del Cnc

Machine Control:  
Zero XYZ  
Zero X  
Zero Y  
Zero Z  
Step Size 1  
X- X+ Y+ Y- Z+ Z-

G54 G55 G56 G57 G58 G59

Colapse Close

X: -16.225 Y: 14.015

3.157 mm

Label1

SimplyLaser

New Open Vectorize Save Mach

Undo Delete Fillet Translate S

Geometry Toolpath

Geometry

X: -16.225 Y: 14.015

### GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
Close

Panic Button

Machine Status:  
Active State:  
**Idle**

X 0.000  
Y 0.000  
Z 0.000

Work Coord's

Show position

Show verbose output

Grbl 0.9j ['\$' for help]  
Grbl 0.9j ['\$' for help]  
[G0 G54 G17 G21 G90 G94 M0 M5 M9 T0 F0. S0.]  
[G0 G54 G17 G21 G90 G94 M0 M5 M9 T0 F0. S0.]  
[G0 G54 G17 G21 G90 G94 M0 M5 M9 T0 F0. S0.]

Machine Control File Mode Macros

File:  
C:\ProgramData\SimplyCam 3\gcode\test.nc

Last processed  
Open g-code

Send

Check gcode mode

Colapse Close

Da File Mode selezionare l'ultimo file G-Code processato

3.157 mm

Label1

SimplyLaser

New Open Vectorize Save Mach

Undo Delete Fillet Translate S

Geometry Toolpath

Geometry

X: -16.225 Y: 14.015

### GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
Close

Panic Button

Machine Status:  
Active State:  
**Idle**

X 0.000  
Y 0.000  
Z 0.000

Work Coord's

Show position

Show verbose output

G90; Use absolute coordinates  
G92; Coordinate Offset  
error: Invalid gcode ID:26  
G00X-6.315Y1.251  
M4

Machine Control File Mode Macros

File:  
C:\ProgramData\SimplyCam 3\gcode\test.nc

Last processed Open g-code

Send How often: 1

Colapse Close

Inviare il file al CNC

3.157 mm

Label1

SimplyLaser

New Open Vectorize Save Mach

Undo Delete Fillet Translate S

Geometry Toolpath

Geometry

X: -16.225 Y: 14.015

### GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
Close

Panic Button

Machine Status:  
Active State:  
**Run**

X: -7.316  
Y: 2.988  
Z: 2.000

Work Coord's

Show position

Show verbose output

G01X-59.151Y-15.789  
G01X-63.551Y-15.789  
G01X-63.549Y4.061  
G03X-63.699Y4.211I-0.15J0.  
G01X-94.Y4.214

Machine Control | File Mode | Macros

File:  
C:\ProgramData\SimplyCam 3\gcode\test.nc

Last processed | Open g-code

Send | How often: 1

Pause | Abort

Sent / Tot.Rows 17 / 156

Check gcode mode

Colapse | Close

3.157 mm

Label1

SimplyLaser

New Open Vectorize Save Mach

Undo Delete Fillet Translate S

Geometry Toolpath

Geometry

X: -16.225 Y: 14.015

### GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
Close

Panic Button

Machine Status:  
Active State:  
**Run**

X: -26.128  
Y: 4.208  
Z: 2.000

Work Coord's

Show position

Show verbose output

G01X-63.549Y4.061  
G03X-63.699Y4.211I-0.15J0.  
G01X-94.Y4.214  
G03X-95.15Y3.064I0.J-1.15  
G01X-95.15Y-2.269

Machine Control File Mode Macros

File:  
C:\ProgramData\SimplyCam 3\gcode\test.nc

Last processed Open g-code

Send How often: 1

Pause Abort

Sent / Tot.Rows 19 / 156

Check gcode mode

Colapse Close

3.157 mm

Label1

SimplyLaser

New Open Vectorize Save Mach

Undo Delete Fillet Translate S

Geometry Toolpath

Geometry

X: -16.225 Y: 14.015

### GRBL Panel

Connection:  
Port: COM10  
Baud: 115200  
Close

**Panic Button**

Machine Status:  
Active State:  
**Idle**

X **9.000**  
Y **0.000**  
Z **2.000**

Work Coord's

Show position

Show verbose output

G01X0.Y9.246  
G01X0.Y8.246  
M7  
M19  
G00 X0 Y0; home  
G28; home all axes

Machine Control File Mode Macros

File:  
C:\ProgramData\SimplyCam 3\gcode\test.nc

Last processed Open g-code

Send How often: 1

Pause Abort

Sent / Tot.Rows 156 / 156

Check gcode mode

**Fatto!**

Colapse Close

3.157 mm

Label1