

SimplyCam Percorso Ut. Tasca

Questo tutorial mostra come aprire un file DXF e creare il percorso utensile per rimuovere il materiale contenuto in un profilo chiuso.


Geometry Toolpath

- Machine: Mach2
 - Pocket - T3
 - Parameter
 - Toolpath
 - Pocket - T1
 - Parameter
 - Toolpath

```

gcEditor v 0.9.9.2
File Edit Text Tools Help
C:\ProgramData\SimplyCam 3\gcode\test.nc
%
N1 (POST PROCESSOR: MACH2-3)
N2 (TEST.NC)
N3 G21 (UNITS: MM)
N4 G00 G17 G40 G49 G80 G90
N5 G64 (Constant Velocity Mode)
N6 T3 M6 (TLDIA=4)
N7 G91.1 (IJ Incremental mode for a
N8 G00 X95.079 Y5.1 M03
N9 G43 H3 Z2.
N10 G01 Z-2. F50.0
N11 G01 X82.523 Y5.1 Z-2. F100.0
N12 X51.412 Y7.5
N13 X95.17
N14 X95.235 Y7.818
N15 G00 Z2.
N16 X96.032 Y9.9
  
```

In 0 col 0



Change Post

Show/Hide to

Navigation icons: back, forward, stop, play, and a slider. Current Z: 0

X: 68.582 Y: -39.497

29m, 49s


10.005 mm

New Open Vectorize Save Machining Settings Help Close Create point Line Endpoints Rectangle Circle Ct + Pt

Undo Delete Fillet

Geometry Toolpath

Machine: Mach2-3



Attenzione:

**Le macchine a controllo numerico sono potenzialmente pericolose.
Il post-processore può generare codice non idoneo al controllo della
macchina.**

Controllare il file G-code prima di inviarlo alla macchina CNC.

Change Post

Run Post

Show/Hide toolpaths

X: -11.869 Y: -12.121

Open file (*.snc;*.dxf;*.stl;*.svg;*.bmp;*.jpg)

SNAP
OFF

90°

Grid

Ortho

Grid

STOP

Check


Current layer: 0

Label1

3.157 mm

3.157
mm

Click sul bottone Carica per importare il file Dxf.



Change Post

Run Post

Show/Hide toolpaths

X: -11.869 Y: -12.121

Open file (*.snc;*.dxf;*.stl;*.svg;*.bmp;*.jpg)

SNAP OFF

90°

Grid

Grid

Grid

STOP

Checkmark

Current layer: 0

Label1

3.157 mm

Click sul bottone Carica per importare il file Dxf.

- Look in: samples
- | Name |
|-----------------------|
| LatheSampleRouFin.DXF |
| LatheSampleRouFin.SNC |
| LatheSampleRough.SNC |
| PIZZALED.JPG |
| SAMPLE_CONTOUR.DXF |
| Sample_ipad-base.DXF |
| SAMPLE_LABEL.JPG |
| SAMPLE_MULTI_OP.DXF |
| SAMPLE_POCKET.DXF |
| SAMPLE_POCKET.SNC |
| SAMPLE_...JPG |

Selezionare nella cartella "..\SimplyCam 3\Samples\" il file SAMPLE_POCKET.DXF.

Change Post

Run Post

Show/Hide toolpaths

X: -11.869 Y: -12.121

Open file (*.snc,*.dxf,*.stl,*.svg,*.bmp,*.jpg)

SNAP OFF

90°

Grid

Grid

Grid

STOP

Green checkmark

Current layer: 0

Label1

3.157 mm

Open Dxf

Dxf info

- Dxf info - Version: 12
- Name: SAMPLE_POCKET.DXF
- First vertex: X0, Y0
- Second vertex: X109.128, Y61.973
- Width: 109.128
- Height: 61.973
- Points: 0
- Lines: 19
- Arcs: 17
- Circle: 6
- Polyline: 0
- Spline: 0
- Ellipse: 0
- Text: 0

Scale to:

Width(X): 109.128 mm

Height(Y): 61.973 mm

Thickness(Z): 0.0 mm

Keep ratio

Reference setting:

Use drawing origin and orientation

Select Pt.

Reference point X: 0

Reference point Y: 0

Reference point Z: 0

Rotate:

Angle: 0

Use Dxf color index

Autozoom

Apply Done

Show/Hide toolpaths

X: 37.688 Y: -9.182

Define dimension and reference point


11.884 mm

Current layer: 0 Label1

Il dialogo viene visualizzata con le informazioni e la dimensione del disegno.

Scalare la dimensione disegno se desiderata.

Definire il punto di riferimento e premere il pulsante "Applica/Finito".



Il disegno è visualizzato nella area grafica con griglia, direzione assi, origine e informazioni scala.

New Open Vectorize Save Machining Settings Help Close Create point Line Endpoints Rectangle Circle Ct + Pt


Undo Delete Fillet Translat

Geometry Toolpath

Machine: Mach2-3

- New
- Contour
- Pocket
- Drill
- Write
- Parallel
- Edit G-Code
- Grbl Panel

Premere "Tasca" dal menu "Lavorazioni"



Change Post Run Post Show/Hide toolpaths

11.884 mm

X: -8.185 Y: 43.109

SNAP OFF 90° Grid Snap Stop Checkmark Current layer: 0 Label1

Pocket

Tools Profiles Parameters

Tools List:
C:\ProgramData\SimplyC... \Tools_mm.tlb

- Flat(Diam. 2)
- Flat(Diam. 3)
- Flat(Diam. 4)
- Flat(Diam. 5)
- Flat(Diam. 6)
- Flat(Diam. 8)
- Flat(Diam. 10)
- Drill(Diam. 3)
- Drill(Diam. 4)
- Drill(Diam. 6)
- Conical(Diam. 0.3)
- Conical(Diam. 0.5)
- Spherical(Diam. 4)
- Flat(Diam. 5)

Open library Save library

Tool definition:

Plunge rate: 50

Name: Flat

Type: Flat


Diameter (d): 4

Length: 1.875

Depth pass: 0

Add to lib. Modify in lib.

Nella scheda Utensili, cliccare nella lista per selezionare l'utensile



Show/Hide toolpaths

11.884 mm

X: -8.185 Y: 26.471

Define tool, speed and feeds

Pocket


Tools Profiles Parameters

TOOLS LIST:
C:\ProgramData\SimplyC... \Tools_mm.tlb

- Flat(Diam. 2)
- Flat(Diam. 3)
- Flat(Diam. 4)
- Flat(Diam. 5)
- Flat(Diam. 6)
- Flat(Diam. 8)
- Flat(Diam. 10)
- Drill(Diam. 3)
- Drill(Diam. 4)
- Drill(Diam. 6)
- Conical(Diam. 0.3)
- Conical(Diam. 0.5)
- Spherical(Diam. 4)
- Flat(Diam. 5)


Open library Save library

Tool definition:



Tool number: 3
Speed: 1500
Spindle CW
Feed rate: 100
Plunge rate: 50
Coolant
Name: Flat
Type: Flat
Diameter (d): 4
Length: 1.875
Depth pass: 0
Add to lib. Modify in lib.

..ed impostare la velocita e l'avanzamento dell'utensile.




Show/Hide toolpaths

11.884 mm

X: -8.185 Y: 26.471

Define tool, speed and feeds



Click sulla scheda "Profili"

Pocket

Tools | **Profiles** | Parameters

Profiles definition:

Layer priority

Go To

Last | All

Select | WinSelect

Chain | Reverse

Unselect last | Unselect all | Chains Manager


Cutter Compensation:

Offset Side: Auto

Offset distance: 2

Start in mid

Cutter compensation in Cnc (G41/G42)



Show/Hide toolpaths

X: -8.185 Y: 26.471

Select the profile, cutter compensation and Enter/Exit



Current layer: 0 Label1

11.884 mm

Pocket

Tools Profiles Parameters

Profiles definition:

Layer priority

Go To

Last All

Select WinSelect

Chain

Unselect last Unselect all

Cutter Compensation:


Offset Side: Auto

Offset distance: 2

Start in mid

Cutter compensation in Cnc (G41/G42)

..... e premere il bottone "Catena".



Show/Hide toolpaths

11.884 mm

X: -8.185 Y: 26.471

Select the profile, cutter compensation and Enter/Exit

Pocket

Tools Profiles Parameters

Profiles definition:

Layer priority


Cutter Compensation:

Offset Side: Auto


Start in mid

Cutter compensation in Cnc (G41/G42)

Click sulla geometria vicino al punto iniziale come indicato dal quadrato rosso.



Show/Hide toolpaths



11.884 mm

X: 41.967 Y: 23.856

Use the mouse to select an object.

Pocket

Tools Profiles Parameters

Profiles definition:

Layer priority

Go To

Last All

Select WinSelect

Chain Reverse

Unselect last Unselect all Chains Manager

1 closed chain

Cutter Compensation:


Offset Side: Auto

Offset distance: 2


Start in mid

Cutter compensation in Cnc (G41/G42)

Appaiono due frecce gialle.
La freccia lunga in il punto di partenza e
la direzione del percorso.
La freccia piccola indica la direzione della
compensazione
Il limite blu è il profilo concatenato



Show/Hide toolpaths



11.884 mm

X: 43.393 Y: 26.471

Pocket

Tools Profiles Parameters

Profiles definition:

Layer priority

Go To

Last

Select

Chain

Unselect last Unselect all Chains Manager

1 closed chain

Cutter Compensation:

Offset Side: Auto

Offset distance: 2

Start in mid

Cutter compensation in Cnc (G41/G42)

Premere ancora il bottone "Catena" per definire un altro profilo.



Show/Hide toolpaths

11.884 mm

X: -6.759 Y: -10.846

Pocket

Tools Profiles Parameters

Profiles definition:

Layer priority

Go To

Last All

Select WinSelect

Chain Reverse

Unselect last Unselect all Chains Manager

2 closed chain

Cutter Compensation:

Offset Side: Auto

Offset distance: 2

Start in mid

Cutter compensation in Cnc (G41/G42)



Show/Hide toolpaths

11.884 mm

X: 55.752 Y: 27.421

Pocket

Tools Profiles Parameters

Profiles definition:

Layer priority

Go To

Last All

Select Chain

Unselect last Unselect all

2 closed chain

Cutter Compensation:


Offset Side: Auto

Offset distance: 2

Start in mid

Cutter compensation in Cnc (G41/G42)

Premere ancora il bottone "Catena" per definire un altro profilo.



Show/Hide toolpaths

8.583 mm

X: 5.517 Y: 32.547

Pocket

Tools Profiles Parameters

Profiles definition:

Layer priority

2 closed chain


Cutter Compensation:

Offset Side: Auto

Start in mid

Cutter compensation in Cnc (G41/G42)

Click sulla nuova geometria come indicato dal quadrato rosso.



Show/Hide toolpaths

8.583 mm

X: 37.961 Y: 34.95

Use the mouse to select an object.

Pocket

Tools Profiles Parameters

Profiles definition:

Layer priority

Go To

Last All

Select WinSelect

Chain Reverse

Unselect last Unselect all Chains Manager

3 closed chain

Cutter Compensation:

Offset Side: Auto

Offset distance: 2

Start in mid

Cutter compensation in Cnc (G41/G42)

Questa è un'altra tasca.



Show/Hide toolpaths

8.583 mm

X: 18.048 Y: 23.621

Pocket

Tools Profiles **Parameters**

Pocket parameters:

Feed Plane: 2

Top of part: 0

Depth: -1

Depth increment: 1

Depth Entry: None Keep tool down

Stock to leave: 0

Step over (%): 60

N. 1


Finish cuts size: 0.0

Lead In/Out (none)


Pocket type: ZigZag

Angle: 0

Transform Calculate Cancel



Click sulla scheda "Parametri" e impostare i seguenti parametri:



X: -5.163 Y: -1.559

Set the cutting parameters and press the 'Calculate' button

Pocket

Tools Profiles Parameters

Pocket parameters:

Feed Plane: 2

Top of part: 0

Depth: -5

Depth increment: 1

Depth Entry: None Keep tool down

Stock to leave: 0

Step over (%): 60

N. 1


Finish cuts size: 0.0

Lead In/Out (none)

Pocket type: ZigZag

Angle: 0


Transform Calculate Cancel



Create point Line Endpoints Rectangle Circle Ct + Pt

Zoom In Zoom back Zoom window Pan Redraw Top Front Side Iso

Profondità:
imposta la profondità finale della
lavorazione (assoluta).



Change Post Run Post

Show/Hide toolpaths

X: -5.163 Y: -1.559

Set the cutting parameters and press the 'Calculate' button

SHAP OFF 90° [Grid] [Snap] [Stop] [Green Checkmark]

Current layer: 0 Label1

8.424 mm

Pocket

Tools | Profiles | Parameters

Pocket parameters:

Feed Plane: 2

Top of part: 0

Depth: -5

Depth increment: 2

Depth Entry: None Keep tool down

Stock to leave: 0

Step over (%): 60

N: 1


Finish cuts size: 0.0

Lead In/Out (none)

Pocket type: ZigZag

Angle: 0


Transform Calculate Cancel



Create point | Line Endpoints | Rectangle | Circle Ct + Pt

Zoom In | Zoom back | Zoom window | Pan | Redraw | Top | Front | Side | Iso

Passata in Z:
imposta l'asportazione massima per ogni
passata in profondità.



Change Post | Run Post

Show/Hide toolpaths

X: -5.163 Y: -1.559

Set the cutting parameters and press the 'Calculate' button

SNAP OFF | 90° | Grid | Label1

Current layer: 0

8.424 mm

Pocket

Tools | Profiles | Parameters

Pocket parameters:

Feed Plane: 2

Top of part: 0

Depth: -5

Depth increment: 2

Depth Entry: Ramp auto

None
Ramp auto
Helix auto

Step over (%): 60

N: 1


Finish cuts size: 0.0

Lead In/Out (none)

Pocket type: ZigZag

Angle: 0

Transform Calculate Cancel



Penetrazione:
imposta il tipo di penetrazione

Create point | Line Endpoints | Rectangle | Circle Ct + Pt

Zoom In | Zoom back | Zoom window | Pan | Redraw | Top | Front | Side | Iso



Pocket

Tools

Profiles

Parameters

Pocket parameters:

Feed Plane: 2

Top of part: 0

Depth: -5

Depth increment: 2

Depth Entry: Ramp auto

 Keep tool down

Stock to leave: 0

Step over (%): 60

N. 1

Finish cuts size: 0.1

Lead In/Out (none)


Pocket type: ZigZag

Angle: 0

Transform

Calculate

Cancel



Numero di passate di finiture/ Asportazione per ogni finitura:
imposta il numero e l'asportazione delle passate di finitura sulle pareti.

Show/Hide toolpaths

X: -5.163 Y: -1.559

Set the cutting parameters and press the 'Calculate' button

SNAP OFF

90°

Grid

Snap

Grid

STOP

Check

Current layer: 0

Label1

8.424 mm

Pocket

Tools Profiles Parameters

Pocket parameters:

Feed Plane: 2

Top of part: 0

Depth: -5

Depth increment: 2

Depth Entry: Ramp auto Keep tool down

Stock to leave: 0

Step over (%): 60


N: 1 Finish cuts size: 0.1

Lead In/Out (none)

Pocket type: Spiral


Spiral In-Out: ZigZag
Spiral

Transform Calculate Cancel



Create point Line Endpoints Rectangle Circle Ct + Pt

Zoom In Zoom back Zoom window Pan Redraw Top Front Side Iso



Tipo Tasca:
definisce il metodo di taglio
nella sgrossatura della tasca.

Pocket

Tools Profiles Parameters

Pocket parameters:

Feed Plane: 2

Top of part: 0

Depth: -5

Depth increment: 2

Depth Entry: Ramp auto Keep tool down

Stock to leave: 0

Step over (%): 60


N. 1 Finish cuts size: 0.1

Lead In/Out (none)

Pocket type: Spiral


Spiral In-Out

Transform Calculate Cancel



Create point Line Endpoints Rectangle Circle Ct + Pt

Zoom In Zoom back Zoom window Pan Redraw Top Front Side Iso




Premere il bottone "Calcola".

X: -5.163 Y: -1.559

Set the cutting parameters and press the 'Calculate' button

SNAP OFF 90° Grid Snap Stop Green Current layer: 0 Label1


8.424 mm



Geometry | Toolpath


- Machine: Mach2-3
 - Pocket - T3 D.4 (Flat)**
 - Parameters
 - Toolpath (600)

La nuova operazione "Tasca" è creata nel Gestore Operazioni e il percorso utensile è visualizzato nell'area grafica.



Change Post Run Post

Show/Hide toolpaths




Estimate machining time = 1h, 00m, 34s

11.884 mm

X: -7.709 Y: 67.59

SNAP OFF | 90° | Grid | Stop | Current layer: 0 | Label1




Geometry | Toolpath

- Machine: Mach2-3
 - Pocket - T3 D.4 (Flat)
 - Parameters
 - Toolpath (600)


- Change parameters
- Show toolpath
- Simulate

Click con il tasto destro del mouse sulla voce "Percorso Ut." e selezionare "Simula" dal menu a discesa.



Change Post Run Post

Show/Hide toolpaths



Estimate machining time = 1h, 00m, 34s

11.884 mm

X: -7.709 Y: 67.59


The screenshot displays the SimplyCam software interface. A 'Simulate' dialog box is open in the foreground, showing a 'Z Depth' slider with a yellow bar at the top (labeled 'Rapido') and a blue bar at the bottom (labeled 'Lento'). The 'Current Z' is set to 2. The dialog includes a 'Line:600/600' indicator, a 'Play / Stop' button, and several checkboxes: 'Show Tool', 'Show True Width', 'GCode simulation', and 'Solid simulation'. A yellow callout box points to the 'Play / Stop' button and contains the following text:

Il dialogo Simulazione è visualizzato.
 Premere il tasto "Riavvolge".
 Spostare il cursore vicino a posizione "Lenta".
 Premere il pulsante "Play" per simulare il percorso utensile nell'area grafica.
 L'indicatore del pannello "Z Corrente", riflette la posizione Z dell'utensile (giallo = Rapido, Azzurro = Lavoro).

The background shows a 2D toolpath visualization of a pocket. The toolpath is color-coded: red for the start and end of the path, cyan for the main cutting path, and green for the outer boundary. A coordinate system (X, Y, Z) is visible. At the bottom, the 'Estimate machining time = 1h, 00m, 34s' is displayed, along with a scale bar of 11.884 mm. The status bar at the bottom shows 'X: -7.709 Y: 67.59', 'Current layer: 0', and 'Label1'.

Simulate

Z Depth:



Current Z: 2


Line: 600/600

Navigation buttons: <<< << >> >>>

Show Tool
 Show True Width
 GCode simulation
 Solid simulation

Simulation controls: Play, Stop, Step Back, Step Forward, Progress bar

Simula percorso utensile con larghezza Utensile



Change Post Run Post

Show/Hide toolpaths


Estimate machining time = 1h, 00m, 34s

11.884 mm

X: -7.709 Y: 67.59

Simulate

Z Depth:



.....
.....
.....
.....
.....

Line:600/600

⏪ ⏩ ⏴ ⏵ ⏶ ⏷

Show Tool
 Show True Width
 GCode simulation


Solid simulation

⏪ ⏩ ⏴ ⏵ ⏶ ⏷

| | |
|--------|--------|
| Origin | Size |
| X: 0 | L: 110 |
| Y: 0 | W: 65 |
| Z: 0 | H: 7 |

Help Close Create point Line Endpoints Rectangle Circle Ct + Pt

Aut zoom Zoom In Zoom back Zoom window Pan Redraw Top Front Side Iso



Change Post Run Post

Show/Hide toolpaths

Estimate machining time = 0h, 00m, 00s

11.884 mm

X: 32.23 Y: -18.677

SNAP OFF 90° Grid Stop Checkmark Current layer: 0 Label1



Select postprocessor

Post Processor

Mach2-3


Post Mach2/3
Modal G code, XYZ and Feed
Arc defined with IJ Incremental
Tool change (T..M6)
G43H. tool length offset
Cycle G81, G83, G84
Comment (...)
Space between instruction
Block number

Output metric Output inch

Output file extension:


Rapid feedrate:

Edit Ok



Geometry Toolpath

- Machine: Mach2-3
 - Pocket - T3 D
 - Parameter
 - Toolpath
 - Pocket - T1 D
 - Parameter
 - Toolpath



Change Post Run Post

Show/Hide toolpaths

Premere "Esegue Post" e selezionare la cartella e il nome del file NC.

Estimate machining time = 0h, 29m, 49s

11.884 mm

X: -8.185 Y: 26.708

Define the postprocessor

SHARP OFF 90° [Grid] [Snap] [STOP] [Check] Current layer: 0 Label1


```


gcEditor v 0.9.9.2
File Edit Text Tools Help
C:\ProgramData\SimplyCam 3\gcode\test.nc
N498 X13.642 Y49.622
N499 G03 X13.863 Y50.367 I-7.672
N500 G00 Z2.
N501 X8.729 Y44.679
N502 G01 Z-2. F50.0
N503 G01 X5.9 Y41.851 Z-2.116 F100.0
N504 X8.729 Y44.679 Z-2.325
N505 X5.9 Y41.851 Z-2.535
N506 X8.729 Y44.679 Z-2.744
N507 X5.9 Y41.851 Z-2.953
N508 X8.729 Y44.679 Z-3.163
N509 X5.9 Y41.851 Z-3.372
N510 X8.729 Y44.679 Z-3.581
N511 X5.9 Y41.851 Z-3.791
N512 X8.729 Y44.679 Z-4.
N513 X5.1 Y41.05
N514 Y44.255
N515 G03 X8.555 Y44.617 I0.905 J8.04
N516 G00 Z2.
N517 X5. Y44.366
N518 G01 Z-4. F50.0
N519 G01 X5. Y19.843 Z-4. F100.0
N520 G02 X13.837 Y10.298 I0.999 J-7.
N521 G01 X32.163 Y8.885
N522 G03 X32.646 Y8.874 I0.336 J4.26

```

Current Z: -2.32

In 505 col 0

L'editor con il file G-Code processato.



10.005 mm

gcEditor v 0.9.9.2

File Edit Text Tools Help


C:\ProgramData\SimpleCam 3\gcode\test.nc

```

N498 X13.642 Y49.622
N499 G03 X13.863 Y50.367 I-7.672 J2.
N500 G00 Z2.
N501 X8.729 Y44.679
N502 G01 Z-2. F50.0
N503 G01 X5.9 Y41.851 Z-2.116 F100.0
N504 X8.729 Y44.679 Z-2.325
N505 X5.9 Y41.851 Z-2.535
N506 X8.729 Y44.679 Z-2.744
N507 X5.9 Y41.851 Z-2.953
N508 X8.729 Y44.679 Z-3.163
N509 X5.9 Y41.851 Z-3.372
N510 X8.729 Y44.679 Z-3.581
N511 X5.9 Y41.851 Z-3.791
N512 X8.729 Y44.679 Z-4.
N513 X5.1 Y41.05
N514 Y44.255
N515 G03 X8.555 Y44.617 I0.905 J8.04
N516 G00 Z2.
N517 X5. Y44.366
N518 G01 Z-4. F50.0
N519 G01 X5. Y19.843 Z-4. F100.0
N520 G02 X13.837 Y10.298 I0.999 J-7.
N521 G01 X32.163 Y8.885
N522 G03 X32.646 Y8.874 I0.336 J4.26
    
```

Current Z: -2.32

In 505 col 0



Anche dentro all'Editor è possibile simulare il file G-code in formato ISO.

