


SimplyCam

Tutorial 4 - Open Dxf file and create multiple toolpaths (Contour, Pocket and Drill).


In this tutorial you will open a Dxf file and create the toolpath that cut the external of the part, another toolpath to remove the material contained in a closed profile, and a tool-change with the drill operation.




Caution:

CNC machines are potentially dangerous. The post-processor can output code unsuitable for your machine's control. Check the Nc file before sending it to a CNC machine.


1. Open the Dxf file with the "Open" button.




2. Select in "..\SimplyCam\Sample\" folder the **SAMPLE_POCKET.DXF** file.
3. The Info panel will appear with the info and dimension of image. Press "Next Page" button.




- Define the reference point of the drawing and press "Done" button.




- Turn in the "Off" state the button "Show grid" and "Show Axis".



- 6. The drawing is displayed in graphic area without the grid, the axis direction, the origin and the scale info.




- Press "Nc Program" button to go in toolpath section.




- This section contain 5 pages:
- Page 1: File/Postprocessor definition
 - Page 2: Tool/Operation definition
 - Page 3: Profile/Cutter compensation selection
 - Page 4: Cutting parameter setting
 - Page 5: Nc file simulating or editing




- Select the postprocessor of your Cnc machine.




9. Press "New" button to create new toolpath.



10. Type "test" in the Windows file dialog.




11. Press "Next Pg(2)" button.



12. In Tool section press "Select" button to retrieve a tool from a tool library or create a new tool.


(2) Tool description:
Flat (Dia 8)




Tool Number: 1

Speed and feed
Speed: 2500
Feed rate: 150
Plunge rate: 75

Geometry
Diameter: 8

 Select ...

 Edit ...

Operation:


Contour

Drill


Pocket

◀ Prev Pg (1) Next Pg (3) ▶


13. Click in the Tool List to select the Flat tool with **diameter 8**. Set feeds and speed of the tool. Press the "OK" button.




14. In the Operation section, select "Contour" and press "Next Pg(3)".




15. The "Profile definition" page appears. Press the "Chain" button.




16. Pick the geometry near to start point as indicate by red square.




17. The yellow arrow appears to indicate the start point of contour and the direction of contour.
The blue boundary is the chained profile.




18. In the "Profile definition" press the "Reverse" button and press "Next Pg(3)".




19. The new direction of the chain is showing.




20. In the "Cutter compensation" section, set the "Offset Side" on Outside.




21. Another yellow arrow, smaller than previous, appears to indicate the direction of cutter compensation.
The long arrow = Toolpath direction
The small arrow = Cutter compensation direction.



22. Set the "Lead in" and "Lead out".




23. And then press "Next Pg(4)" button.



24. The "Contour parameter" page appear. Set up the following parameters:

25. **Feed plane:** set the height that the tool rapids to (G0) before changing to the feed rate (G1) to enter in the part (absolute).

(4) Contour parameter:



2 cuts of 3.000


Depth increment: 3

Stock to leave: 0

N. 1 Rough cuts of size: 0.0

N. 0 Finish cut of size: 0.0

Write EOF

 Calculate

← Prev Pg (3) Next Pg (5) →

Feed Plane:	2
Top of part:	0
Depth:	-6
Depth increment:	3
Stock to leave:	0
N. 1 Rough cuts of size:	0.0
N. 0 Finish cut of size:	0.0

26. **Top of part:** set the height of the piece in the Z axis (absolute).

(4) Contour parameter:

Feed Plane: 2

Top of part: 0

Depth: -6

Depth increment: 3

Stock to leave: 0

N. 1 Rough cuts of size: 0.0

N. 0 Finish cut of size: 0.0

Write EOF

Calculate

Prev Pg (3) Next Pg (5)

Detailed description: This is a software dialog box titled '(4) Contour parameter:'. It features a central 3D diagram of a cylindrical part being machined by a tool. A red horizontal line indicates the 'Top of part' at Z=0. The 'Depth' is set to -6, and the 'Depth increment' is 3, resulting in '2 cuts of 3.000'. The 'Feed Plane' is set to 2. Below the diagram are several input fields: 'Top of part' (0), 'Depth' (-6), 'Depth increment' (3), 'Stock to leave' (0), 'N. 1 Rough cuts of size' (0.0), and 'N. 0 Finish cut of size' (0.0). There is a checked 'Write EOF' checkbox and a 'Calculate' button. At the bottom, there are navigation arrows for 'Prev Pg (3)' and 'Next Pg (5)'.

27. **Depth:** set the final machining depth (absolute).

(4) Contour parameters:

Feed Plane: 2

Top of part: 0

Depth: -6

Depth increment: 1

Stock to leave: 0

N. 1 Rough cuts of size: 0.0

N. 0 Finish cut of size: 0.0

Write EOF

Calculate

Prev Pg (3) Next Pg (5)

Detailed description: This is a software dialog box titled '(4) Contour parameters:'. It features a central 3D diagram of a cylindrical part being machined by a tool. A red horizontal line indicates the 'Top of part' at Z=0. The 'Depth' is set to -6, and the 'Depth increment' is 1, resulting in '6 cuts of 1.000'. The 'Feed Plane' is set to 2. Below the diagram are several input fields: 'Top of part' (0), 'Depth' (-6), 'Depth increment' (1), 'Stock to leave' (0), 'N. 1 Rough cuts of size' (0.0), and 'N. 0 Finish cut of size' (0.0). There is a checked 'Write EOF' checkbox and a 'Calculate' button. At the bottom, there are navigation arrows for 'Prev Pg (3)' and 'Next Pg (5)'.

28. **Depth increment:** set the maximum amount of material to remove for each Z cut.

(4) Contour parameters:

Feed Plane: 2

Top of part: 0

Depth: -6

Depth increment: 0.5

Stock to leave: 0

N. 1 Rough cuts of size: 0.0

N. 0 Finish cut of size: 0.0

Write EOF

Calculate

Prev Pg (3) Next Pg (5)

Detailed description: This is a screenshot of a software dialog box titled '(4) Contour parameters:'. It features a small diagram on the left showing a vertical tool cutting into a block of material. To the right of the diagram are several input fields: 'Feed Plane' (2), 'Top of part' (0), 'Depth' (-6), 'Depth increment' (0.5), and 'Stock to leave' (0). Below these are two rows for 'Rough cuts of size' and 'Finish cut of size', each with a dropdown menu (set to 'N. 1' and 'N. 0' respectively) and a value field (both 0.0). At the bottom right, there is a 'Write EOF' checkbox which is checked, and a 'Calculate' button. Navigation buttons for 'Prev Pg (3)' and 'Next Pg (5)' are at the very bottom.

29. **Write EOF:** Turn "Off" this parameter for not write in the Nc file the "End Of File" section (typically M2 or M30) .

(4) Contour parameters:

Feed Plane: 2

Top of part: 0

Depth: -6

Depth increment: 3

Stock to leave: 0

N. 1 Rough cuts of size: 0.0

N. 0 Finish cut of size: 0.0


Write EOF

Calculate


Prev Pg (3) Next Pg (5)

Detailed description: This is a screenshot of the same software dialog box as above. The 'Depth increment' field is now set to 3. The 'Write EOF' checkbox is now unchecked. All other parameters and the layout remain the same as in the previous screenshot.


30. Press the "Calculate" button to machining the chained geometry with the cutting parameters.




31. The "Nc File" page is displayed and in the graphic area the toolpath is simulated.




32. Press the "Rewind" button.




33. Move the slider near to slow position.




34. Press the "Play" button to simulate the toolpath (Yellow=Rapid, Cyan=Feed) in the graphic area.




35. The first toolpath (Contour) is simulated.
The "Z Depth" panel indicator reflect the actual Z tool position (Yellow=Rapid, Cyan=Feed).




36. Press the "Prev Pg(4)" button.




37. "Remove the last operation created?"
No, the contour toolpath is correct, we want to preserve it.




38. Press the "Prev Pg(3)" button and Press the "Prev Pg(2)" button.




39. In the Operation section, select "Pocket" and press "Next Pg(3)".




40. The "Profile definition" page appear. Press the "Unselect" button to remove the last chain.




41. Press the "Chain" button.




42. Pick the geometry near to start point as indicate by red square.



43. Two yellow arrows appear.
The long arrow indicate the start point of boundary and the direction of toolpath.
The small arrow indicate the side of toolpath.
The blue boundary is the chained profile.



44. Press the "Next Pg(4)" button.



45. The "Pocket parameters" page appears. Set up the following parameters:

46. **Feed plane:** set the height that the tool rapids to (G0) before changing to the feed rate (G1) to enter in the part (absolute).

(4) Pocket parameter:

Feed Plane: 2

Top of part: 0

Depth: -3

Depth increment: 1

Stock to leave: 0

Step over(%): 50

N. 0

Finish cuts size: 0

Pocket type: Spiral

Spiral In-Out

Write EOF Calculate

Prev Pg (3) Next Pg (5)

47. **Top of part:** set the height of the piece in the Z axis (absolute).

(4) Pocket parameter:

Feed Plane: 2

Top of part: 0

Depth: -3

Depth increment: 1

Stock to leave: 0

Step over(%): 50

N. 0

Finish cuts size: 0

Pocket type: Spiral

Spiral In-Out

Write EOF Calculate

Prev Pg (3) Next Pg (5)

48. **Depth:** set the final machining depth (absolute).

(4) Pocket parameters:

Feed Plane: 2

Top of part: 0

Depth: -4

Depth increment: 1

Stock to leave: 0

Step over(%): 50

N. 0 Finish cuts size: 0

Pocket type: Spiral

Spiral In-Out

Write EOF Calculate

← Prev Pg (3) Next Pg (5) →

49. **Depth increment:** set the maximum amount of material to remove for each Z cut.

(4) Pocket parameters:

Feed Plane: 2

Top of part: 0

Depth: -4

Depth increment: 2

Stock to leave: 0

Step over(%): 50

N. 0 Finish cuts size: 0

Pocket type: Spiral


Spiral In-Out

Write EOF Calculate

← Prev Pg (3) Next Pg (5) →

50. **Write EOF:** Turn "Off" this parameter for not write in the Nc file the "End Of File" section (typically M2 or M30) .


(4) Pocket parameters:



Feed Plane: 2
Top of part: 0
Depth: -4
Depth increment: 2
Stock to leave: 0
Step over(%): 50
N. 0 Finish cuts size: 0
Pocket type: Spiral
Spiral In-Out
Write EOF Calculate
Prev Pg (3) Next Pg (5)


51. Press the "Calculate" button to machining the chained geometry with the cutting parameters.

(4) Pocket parameters:



Feed Plane: 2
Top of part: 0
Depth: -4
Depth increment: 2
Stock to leave: 0
Step over(%): 50
N. 0 Finish cuts size: 0
Pocket type: Spiral
Spiral In-Out
Write EOF **Calculate**
Prev Pg (3) Next Pg (5)


52. The "Nc File" page is displayed and in the graphic area the toolpath is simulated.




53. Press the "Rewind" button.




54. Press the "Play" button to simulate the toolpath (Yellow=Rapid, Cyan=Feed) in the graphic area.




55. In the graphic area the first Contour toolpath and the second Pocket toolpath are simulated.




56. Press the "Prev Pg(4)" button.




57. "Remove the last operation created?"
No, the pocket toolpath is correct, we want to preserve it.




58. Press the "Prev Pg(3)" button and Press the "Prev Pg(2)" button.



59. In Tool section press "Select" button to retrieve a tool from a tool library or create a new tool.




60. Click in the Tool List to select the Drill tool with **diameter 3**. Set feeds and speed of the tool. Press the "OK" button.




61. Change the number of tool in **2**.

This new number, different from previous, force SimplyCam to generate in next operation the tool change.


Press the "OK" button.




62. In the Operation section, select "Drill" and press "Next Pg(3)".




63. The "Drill points select" page appear.
Press the "All arcs" button to select all the closed arcs in geometry.



69. **Depth:** set the final depth of drilling operation (absolute).




70. **Cycle:** select the drilling cycle.



71. **Depth increment:** set the amount of material to remove for each Z cut.

(4) Drill parameters:



Feed Plane:


Top of part:

Depth:

Cycle:


Depth increment:

Write EOF

 Calculate

72. **Write EOF:** Turn "On" this parameter for write in the Nc file the "End Of File" section (typically M2 or M30). This is the last operation of the example.

(4) Drill parameters:



Feed Plane:


Top of part:

Depth:


Cycle:

Depth increment:


Write EOF

 Calculate


73. Press the "Calculate" button to drilling the definite points with the cutting parameters.



74. The "Nc File" page is displayed and in the graphic area the drilling toolpath is simulated.



75. The Tool-change section is added in Nc file




76. And the EOF (end of file) sequence is added at end of the Nc file.



77. Press the "Rewind" button.



78. Press the "Play" button to simulate the contour, pocket and drill toolpaths in the graphic area.



79. You have successfully created the multi-toolpath example with SimplyCam.



Caution:

CNC machines are potentially dangerous. The post-processor can output code unsuitable for your machine's control. Check the Nc file before sending it to a CNC machine.